

SRM (Shuttle)	Ambient Temperature in °F	Number of damaged O-rings
1	66	0
2	70	1
3	69	0
4	80	0
5	68	0
6	67	0
7	72	0
8	73	0
9	70	0
10	57	1
11	63	1
12	78	0
13	70	1
14	67	0
15	53	3
16	75	0
17	67	0
18	70	0
19	81	0
20	76	0
21	79	0
22	75	2
23	76	0
24	58	1